## **DMV Lane Technician Observation Report**

DMV Technician: Kelly Dornell Pe	osition:	on: 1 or 2			
Station: Dela are 0.4 Date: 12-24-14	Γime: 🥫	7:30	>		
Station: De la real Type Country Darkell Position: 1 or 2  Station: De la real Type Country Position: 1 or 2  Vehicle Make: Ford Model Forgett Year  CYVVP: Problem State Country Problem Numbers					
GVWR: Fuel Type: 6 ns Registration Number:					
Auditor: Cambole Covert/Ove	ert (Circ	(Circle One)			
	,	YES	NO	N/A	
1. Did technician check vehicle paper work and verify VIN num	ber?	6			
2. Was Emissions testing required?		-			
a) Was Emissions testing performed using OBD?		_			
b) Was Emissions testing performed using Analyzer Probe?					
c) Was Emissions testing performed using Paddle(s)?					
d) Was Emissions testing performed using Clip?					
3. Was Catalytic Converter inspection required?				4	
a) Was Catalytic Converter inspection performed?					
4. Was Fuel Tank pressure testing required?				1	
a) Was Fuel Tank pressure testing performed?					
5. Was Fuel Cap pressure testing required?				1	
a) Was Fuel Cap pressure testing performed?					
6. Is this test a <b>Re-check</b> from a prior failure?					
a) Which re-check test is being performed? 1 2 3 (circle one	e)				
b) If this is re-check #3, was repair paperwork verified for wai	ver?				
Sussex County Only					
7. Was Curb Idle testing required?					
a) Was Curb Idle testing performed?					
Comment: De leurse De alei TAL-					
Comment: De leurie De cler Try -	270 0	Vistor	use 1	Hut	
				1	

Original 08/06/2009/TMP